EVACUATION MAP

N

Welding Design Center

EXIT
EXIT
EXIT
EXIT

115

113A
113C
113B

103
102

112

118

101

EXIT

119

105 106

107

101A

110

EXIT

EXIT

STAY SAFE – FOLLOW THESE TIPS:

- Leave the building through the nearest exit.
- In case of fire: do NOT use the elevator – use STAIRS.
- Do NOT return until the "all clear" message has been given.

R. 05/2021